

Harbor



Prepared for:

Arkansas Energy & Environment
Division of Environmental Quality
Office of Water Quality
Permits Branch
5301 Northshore Drive
North Little Rock, Arkansas 72118-5317

PHOTO SUMMARY

CLOSURE OF C&H HOG
FARM WASTE STORAGE
PONDS

AFIN: 51-00164

MT. JUDEA, ARKANSAS

MAY 2020

Prepared by:

Harbor

Environmental | Safety | Engineering
5800 Evergreen Dr.
Little Rock, AR 72205
P: 501.663.8800
F: 501.588.0123
www.harborenv.com

HARBOR PROJECT NO. ADEQ-19436

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 1: Water level of Pond 1 prior to start of work.



Photograph 2: Manhole leading to Pond 1 was filled with concrete to stop any future waste from being added to the ponds from the hog houses.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 3: Liquid waste removed from Pond 1.



Photograph 4: Water level of Pond 1 after one (1) day of pumping liquid waste out.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 5: Water level of Pond 2.



Photograph 6: Removal of liquid waste from Pond 1 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 7: Removal of liquid waste from Pond 1 continued.



Photograph 8: Water level in Pond 2.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 9: Water level in Pond 1.



Photograph 10: Water level in Pond 2.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 11: Removal of liquid waste from Pond 1 continued.



Photograph 12: Pumping of liquid waste from Pond 1 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020

Feb 18, 2020 at 11:57:10 AM



Photograph 13: Pumping of liquid waste from Pond 1 continued.

Feb 20, 2020 at 2:35:09 PM
Mount Judea AR 72655
United States



Photograph 14: Solid waste remains in Pond 1 after liquid waste is removed.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 15: Removal of liquid waste from Pond 2 started.



Photograph 16: Removal of liquid waste from Pond 2 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 17: Pond 1 nearly all liquid waste removed, solid waste remaining. Rainfall resulted in more liquid waste to be removed.



Photograph 18: Removal of liquid waste from Pond 2 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 19: Mixing of Pond 2.



Photograph 20: Pond 1 with nearly all liquid waste removed.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 21: Solid waste in Pond 1 being pushed toward excavator so it may be loaded into dump trailers and transported to a landfill.



Photograph 22: Manhole was filled with sand.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 23: Manhole filled with sand.



Photograph 24: Removal of liquid waste from Pond 2 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 25: Removal of liquid waste from Pond 2 continued.



Photograph 26: Solid waste is removed from from Pond 1.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 27: Removal of solid waste from Pond 1 continued.



Photograph 28: Removal of solid waste from Pond 1 continued.

Photographs

DEQ: Mt. Judea, Arkansas

1/14/2020 - 5/15/2020



Photograph 29: Removal of solid waste from Pond 1 continued.



Photograph 30: Removal of solid waste from Pond 1 continued. Additional rainfall resulted in additional liquid waste in Pond 1.